XYLEM®

INSTALLATION INSTRUCTIONS
ISLANDER™
HUTCH
H-ISLANDER-xxxx

SUGGESTED TOOLS AND MATERIALS


Philips Screwdriver

Leveler

Drill

Tape Measure

Safety Glasses


Plumbers' Putty

HUTCH INSTALLATION

1



2



CARE AND CLEANING OF VANITY
CUIDADO Y LIMPIEZA DE LA VANIDAD

Dust the vanity frequently with a clean, soft, dry, lint-free cloth, as well as polish it on a regular basis. Clean the surface by rubbing in the direction of the grain. Avoid using silicone cleaners and waxes.
Clean up excess water and spills immediately. Use blotting rather than a wiping action. Water left over a long period of time will cause white spots in the finish. Please note that some chemicals may damage the finish.